



test



## Section:

Pos.	Quantity	Spare part No	Description	Kit	Notes	New
------	----------	---------------	-------------	-----	-------	-----

1149

1	1	1911-1019-01	Turn-handle			
2	7	1911-0820-01	Screw			
3	1	1911-0704-02	Connection cable			
4	1	1911-0977-01	Grommet			
5	1	1911-1001-01	Switch			
6	1	1911-0825-01	Condensor			
7	1	1911-1018-01	Helper's handle			
8	1	1911-1014-01	Motorhousing w.tube			
9	1	1911-1017-01	Splash water cap			
10	1	1911-0821-01	Screw			
11	1	1911-1022-01	Internal wiring		1.19 M	
12	1	1911-1023-01	Motor (not stocked)			
13	1	1911-1016-01	Motor plate			
14	3	1911-0824-01	Screw			
15	3	1911-1021-01	Screw			
16	1	1911-1015-01	Safety cover			
17	3	1911-1020-01	Screw			
18	1	1911-0850-01	Cutting head assy			
19	1	1911-0851-02	.Drive plate			
20	1	1911-0852-01	.Spring			
21	1	1911-9004-01	.Spool w.line		K-FÖRP.	
22	1	1911-9005-07	Cutting line (1.2 m		8 M	
22	1	1911-9005-08	Cutting line (1.2 m		15 M	
22	1	1911-9005-04	Cutting line (1.2 m		0.22 KG (190 M)	
23	1	1911-0725-02	.Head cap			

test